

TO BE FILLED BY THE INSPECTING OFFICER
(Asst. Engineer)

Name of School : MES Centroid School Tirur (New block)

1. Name of the Officer : RIN. PT
2. Location : Tirur
3. Period for which the certificate is issued : 2025 - 2026
4. Type of building : Rcc building
5. Nature of defect if any : New block
 - a) Foundation and basement : GF : Class - $6.10 \times 6.10 \times 3.20 - 8$
Toilet - $3.00 \times 6.10 \times 3.20 - 1$
Staff - $3.00 \times 6.10 \times 3.20 - 1$
 - b) Superstructure : Vaandha - $3.10 \times 2.00 \times 3.20 - 1$
" - $7.00 \times 3.00 \times 2.00 - 1$
 - c) Doors and windows : Lobby - $12.30 \times 3.00 \times 3.20 - 1$
Stair - $5.00 \times 3.00 \times 3.20 - 2$
Lobby - $6.00 \times 5.00 \times 3.20 - 1$
 - d) Wood work wrought and put up : FF Class - $6.10 \times 6.10 \times 3.20 - 7$ Nos
Computer lab - $6.10 \times 6.10 \times 3.20 - 1$
Toilet - $3.00 \times 6.10 \times 3.20 - 1$
Staff - $3.00 \times 6.10 \times 3.20 - 1$
Vaandha - $3.10 \times 2.00 \times 3.20 - 1$
" - $7.00 \times 3.00 \times 2.00 - 1$
" - $12.30 \times 3.00 \times 3.20 - 1$
H.M - $6.00 \times 5.00 \times 3.20 - 1$
Stair - $5.00 \times 3.00 \times 3.20 - 2$ Nos
 - e) Roof
 - f) Flooring
 - g) Miscellenious (Cracks if any)
6. Any Major defects notices which will render the building unsafe if any manner : NIL
7. Whether maintenance work have been done : Yes
8. Whether the structure is sound or not for conduction classes : Structure is Sound under Normal wind and weather condition For Conducting classes

Note: 1. The Stability of the structure should be examined also with reference to location altitude intensity of wind expourse to flood etc.

2. Any additional observation if deemed necessary for the certificate may be furnished seperately with the Certificate.

Certified that the School was inspected by me on 02/12/2025 and found to be fit / unfit to conduct classes for the period for the reason stated above.

Place: Tirur

Date: 2/12/2025



Rt
Signature: Asst. Engineer,
(Designation) Tirur Municipality

TO BE FILLED BY THE INSPECTING OFFICER
(Asst. Engineer)

Name of School : MES Central School, Tirur

1. Name of the Officer : Rijai. PT
2. Location : Tirur
3. Period for which the certificate is issued : 2025 - 2026 [Main block]
4. Type of building : RCC building
5. Nature of defect if any :

a) Foundation and basement b) Superstructure c) Doors and windows d) Wood work wrought and put up e) Roof f) Flooring g) Miscellenious (Cracks if any)	<u>GF</u> class room - 6.25x6.40x3.20 - 11 Nos Vaerandha - 8.40x1.80x3.20 - 1 Nos Toilets - 3.00x6.40x3.20 - 2 Nos Shower room - 6.20x5.00x3.20 - 1 Nos Lobby - 6.25x6.00x3.20 - 1 Nos Toilet - 6.25x1.40x3.20 - 6 Nos <u>FF</u> Library - 2.75x6.40x3.20 - 1 Nos Chairman - 17.85x6.40x3.20 - 1 Nos Office - 12.75x6.40x3.20 - 1 Nos Staff - 3.00x6.40x3.20 - 1 Nos Vaerandha - 8.40x1.80x3.20 - 1 Nos Vice principal - 6.25x6.00x3.20 - 1 Nos Toilet - 6.25x1.40x3.20 - 1 Nos Shower - 6.20x5.00x3.20 - 1 Nos <u>SF</u> class room - 6.25x6.40x3.20 - 8 Nos Maths lab - 9.50x6.40x3.20 - 1 Nos Computer lab - 12.75x6.40x3.20 - 1 Nos Class - 3.00x6.40x3.20 - 1 Nos Toilet - 6.25x1.40x3.20 - 1 Nos Vaerandha - 8.40x1.80x3.20 - 1 Nos Shower - 6.25x5.00x3.20 - 1 Nos
--	--
6. Any Major defects notices which will render the building unsafe if any manner : NIL
7. Whether maintenance work have been done property : YES
8. Whether the structure is sound or not for conduction classes : Structure is sound under normal wind and weather conditions for conducting classes

Note: 1. The Stability of the structure should be examined also with reference to location altitude intensity of wind expourse to flood etc.

2. Any additional observation if deemed necessary for the certificate may be furnished seperately with the Certificate.

Certified that the School was inspected by me on 02/12/2025 and found to be fit / unfit to conduct classes for the period for the reason stated above.

Place: Tirur

Date: 2/12/2025




 Signature: Asst. Engineer, 1
 (Designation) Tirur Municipality